PREVAILED	Roll Call No
FAILED	Ayes
WITHDRAWN	Noes
RULED OUT OF ORDER	
ROLLD GOT OF GREEK	

HOUSE MOTION

MR. SPEAKER:

I move that House Bill 1289 be amended to read as follows:

1	Page 1, line 10, after "675 IAC 21-3-1" insert ",".
2	Page 1, line 10, delete "675 IAC 21-3-2," and insert "675
3	IAC 21-3-2".
4	Page 2, line 8, after "order." insert "However, for Rule 8.6.5.8 to
5	be inapplicable to an elevator under this subdivision, the elevator:
6	(A) must:
7	(i) be inspected not less than one (1) time per year by an
8	elevator inspector; and
9	(ii) have a category 1 pressure test, as described in Rule
10	8.11.3.2 of the Safety Code for Elevators and Escalators
11	as specified by ASME A17.1-2000, performed on the
12	elevator not less than one (1) time every six (6) months,
13	one (1) test a year to be performed in the presence of the
14	elevator inspector performing the inspection required by
15	item (i);and
16	(B) must have a static four (4) hour full load test, as
17	described in ASME A17.1-2000, performed by an elevator

MO128903/DI 96+

1	mechanic whenever the elevator has an unexplained loss of
2	hydraulic fluid, and may not be operated again until the
3	elevator mechanic accounts for the unexplained loss of
4	hydraulic fluid.
	(Reference is to HB 1289 as printed February 9, 2005.)
	Representative Thomas

MO128903/DI 96+